

Acus. De
Total 14. 013.93

Description of the quality of the land on the interior sectional lines.

Quantity	Quality	Quantity	Quality
1. 2 Broken, thin spl, Oak timber		1. 2 Good solid timber, Buck & Oak	
2. 2 Similar		2. 2 Good solid timber, Buck & Sugar	
3. 2 Similar		3. 2 Better timber, Buck & Sugar	
4. 4 Similar		4. 2 Good, thick solid timber, Buck & Sugar	
5. 1 Similar		5. 22 Bottom timber, Buck & Oak	
6. 12 Similar		6. 30 Similar	
7. 12 Similar		7. 22 Similar	
8. 7 Similar		8. 20 Similar	
9. 11 Similar		9. 1 Good, good solid timber, Buck & Sugar	
10. 22 Similar		10. 1 Similar	
11. 29 Similar		11. 1 Similar	
		12. 29 Bottom timber, Sugar & Buck	

126

126

Township, & 4 South of the Base Line, Range, & 2 East.

Interior Sectional Corners Described Quarter Section Corners Continued

[illegible]

Encl. on T. 12

Cut out & pasted on
Township Map. See vol 4
by R.M.

It appears that the
information has been
added to plat.

2/9/43
J. H. Harrington

The foregoing subdivisions of fractional sections are truly copied from the original plat in this office.
Surveyor General's Office
Cincinnati October 19th 1893

Sam. Williams
ch. clk.

Compsed

T. 4 S. R. 2 E. 2nd Mer.

131


	5720	4000
	15486	10412
	5720	4000
15	15486	10412
	5720	4000
	10441	25713
	5720	4000
	59497	59497

The foregoing Sub divisions of fractional sections are hereby
 Copied from the Original plats in this Office.
 Surveyor General's Office
 Cincinnati Oct. 17th 1835.

Saml. Williams
 Clk. Genl.



G a B. b C c D. d E e F f 12



Document in a Contract with and instructions from Board
of the United States beginning with the 3rd day of August 1855
and covering the above mentioned practice at Springfield and the
amount on one above stated and recorded in the field 18501 made at
the Office of the Secretary General

Captain John Montgomery
 General Beauregard
 Charleston

4-55295

全日